



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed

PPH

Report Date: 12/08/2014

Mine Name: Black Knight	Permit Number: S/015/0078	Mine Status: Active
Operator Name: Goldterra Inc.	Inspection Date: 12/08/2014	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 10:40 - 11:00 am	Bond Amount: \$7,600
Attendee(s):	Weather:	Bond Escalation: 03/02/2014
Inspection Purpose: Routine inspection		Prior Inspection: 10/30/2014

Conclusions and Recommendations

The purpose of this inspection was to determine if the site would meet the minimum requirements for bond release.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The Operator has not formally requested bond release but did make known to the Division the intention to reclaim the site and apply for bond release.		
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The site was a test pit. No underground openings, highwalls were constructed. No signs or trash were within the permit area.		
3. Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The site will be protected from erosion by backfilling and grading. The contractor walked tracked machinery over the site to create pocks for seeds to collect.		
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>
None on site		
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The road to the site from roads used for other purposes was reclaimed.		
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No topsoil was salvaged prior to mining. Operator used what material was available.		
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

Wayne Western

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M015-Emery/S0150078-BlackKnight/inspections/Insp12082014.pdf



Reclaimed area looking north. Area was blended into the surrounding areas.







Looking west



Looking southwest



Looking south.

		<p>Pit has been filled in and surface roughened.</p>	<p>Access road looking east. Tracks used to prepare ground for seeding.</p>
		<p>The contractor had to do some earthwork on the access road along the gully. The contractor used tracks to create pocks for seeds and moisture to collect.</p>	<p>Parts of the road were pocked.</p>